



MAERSK OIL QATAR AS DRILLING DEPARTMENT SAFETY STATISTICS 2008, Q2 – Q4 2009


Ramada Hotel

May 2009

DOIRC Meeting Q1 2009

MOQ Safety Performance

October 2009 Year to Date



MOQ Safety Performance

Safety Performance second quarter 2009

LWC	Minors (RWC + MTC)	Near Misses
2	2	9

Safety Performance third quarter 2009

LWC	Minors (RWC + MTC)	Near Misses
0	3	8

INCIDENT ALERT - KEY HAWAII

Lost Workday Case – Struck on leg due to uncontrolled movement of Heavy Weight Drill Pipe

What happened:

- A crew member was struck on the leg and got his foot trapped. The accident happened during bundling of heavy weight drill pipes. The injured person was inside the pipe bay when the drill pipes moved in an uncontrolled manner.

What caused it:

- Wrong body position inside bay.
- No Supervisor present at job site.

What was the result:

- After treatment the IP continued job. Later examination onshore showed a fracture in lower leg.



Actions taken to prevent recurrence:

The accident was discussed on pre tour meetings.
The crew was made aware of body positions during handling of heavy loads.beam.
Investigation done by rig contractor.

Synergi Case #621