




شركة الشاهين لخدمات الآبار
Al-Shaheen Well Services Company




All Around You

HSE DOIRC 25th

Nadir Abdullah
QHSE Department



HSE Performance Q2 & Q3






Near Miss

➤ Brief Description:

On 5/Oct/09 Shop hand was told to tie up the slings into the pad eye of the unit, the IP proceeded up on the unit without using safety harness, which in turn he could not be tied off properly.

➤ Root Cause

Rushing



IP was not competent or

NOT trained ????



Is this right????





Letter Points

- All work at height is properly planned and organized
- All work at height takes account of weather conditions that could endanger health and safety
- Those involved in work at height are trained and competent
- The place where work at height is done is safe
- Equipment for work at height is appropriately inspected
- The risks from fragile surfaces are properly controlled
- The risks from falling objects are properly controlled



Thank You
Questions ?

